




Bypass piping being installed at Park Avenue Pumping Station.



A new pump, valves and piping also at Park Avenue Pumping Station.



Video Inspection of a broken pipe on Hutchinson Street before repairs are made.



Video Inspection of same pipe after rehabilitation using Cured-In-Place Pipe (CIPP) lining.